

Analog Clamp Tester

AC Current ,6A/15A/50A/150A/600A
40mm ϕ CT

Model 3000 (CE)



FEATURES

- High accuracy analog display with strong taut band meter.
- Meter lock function.
- AC current ,AC/DC voltage and resistance measurements.
- Conform to IEC safety requirements.

SPECIFICATIONS

| | |
|------------------------|---|
| Safety standard | : IEC 61010-1, IEC 61010-2-032 ,Installation Category III 600V phase to earth. |
| E.M.C. standard | : EN 61326. |
| Display | : Analog taut band meter |
| Jaw opening capability | : 40mm ϕ |
| Current range | : AC 0~6A/15A/50A/150A/600A |
| Accuracy | : $\pm 3\%$ of full scale(50/60Hz) |
| Voltage range | : AC 0~300V/600V DC 0~60V |
| Accuracy | : $\pm 3\%$ of full scale(50/60Hz) |
| Resistance range | : 0~1k Ω /100k Ω (50 Ω /5k Ω center) |
| Accuracy | : $\pm 3\%$ of scale length |
| Temperature | : -50 $^{\circ}$ C to 200 $^{\circ}$ C (Optional thermister sensor) |
| Withstanding voltage | : AC 5500V 1 minute max. (Between the core of CT and outer case) |
| Operating temperature | : 0 $^{\circ}$ C to 40 $^{\circ}$ C, 80%RH max. (Without condensation) |
| Storage temperature | : -10 $^{\circ}$ C to 60 $^{\circ}$ C, 70%RH max. (Without condensation) |
| Power supply | : 1.5V (AM-4,LR03 or AAA) \times 2 |
| Size | : 69(W) \times 210(H) \times 34(D)mm |
| Weight | : Approx. 400g |
| Accessories | : Hard carrying case.....1 Instruction manual.....1 Test lead.....1set Batteries.....2 |
| Option | : MT-3000 thermister sensor probe |